INSPECTION REPORT

PERMIT NUMBER:	BP-15-00397	OWNER'S NAME:	THE PASS
DATE:	10/17/2016	TYPE:	Framing
TIME STARTED:	11:17 AM	INSPECTOR:	Justin Bennett
MAP NUMBER:	22-11-04055-0014		
 Provide engineer ok for 4x10 used in lieu of LSL on S203C Provide header confirmation for stair window Provide engineer fix for rear window on S202C Hydronics not on test Shear P2-2 not complete 			
INSTRUCTIONS: Complete above corrections/Re-Inspection NEXT INSPECTION: Re-Inspection			
RE-INSPECTION FEE	DUE? NO YES		\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:			
	,	<u> </u>	

INSPECTION REQUEST LINE: 509-962-7694

http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506