INSPECTION REPORT

IIIOI ECITORI NEI ORI			
PERMIT NUMBER:	BP-15-00418	OWNER'S NAME:	HOPPE
DATE:	10/13/2016	TYPE:	Framing
TIME STARTED:	12:46 PM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	19-14-01063-0002		
Clip rafter tails adjacent to dormers Draftstop at duct penetration to attic in master wing			
INSTRUCTIONS: Ok to insulate			
NEXT INSPECTION: insulation			
RE-INSPECTION FEE		DAID DRIOP TO SCUE	\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			

INSPECTION REQUEST LINE: 509-962-7694

ADDRESS:

http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506

<u>iessica.contratto</u> @co.kittitas.wa.us