## **INSPECTION REPORT**

OWNER'S NAME: BJORGE

PERMIT NUMBER: BP-15-00443

DATE:	7/21/2015	TYPE:	Post holes
TIME STARTED:	1:42 PM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	17-19-06058-0001		
1. setback	ks ok		
2. post ho	les ok		
INCTRUCTIONS	anno material de la combana		
INSTRUCTIONS: pump water from holes when pouring			
NEXT INSPECTION	<sup>:</sup> final		
RE-INSPECTION FE	E DUE? V NO COURED, RE-INSPECTION FEES MU	YES ST BE PAID PRIOR TO SC	\$ HEDULING A RE-INSPECTION
C	QUESTIONS? PLEASE CONTACT THE	INSPECTOR AT THE FOLL	OWING E-MAIL ADDRESS:
		iessica.contratto @co	
	ECTION REQUEST LINE: <u>www.co</u> 411 N. Ruby Street, Suite 2, Ellensbi		