INSPECTION REPORT

PERMIT NUMBER:	BP-15-00492	OWNER'S NAME:	MERITAGE DEVELOPN
DATE:	6/22/2016	TYPE:	Final
TIME STARTED:	11:35 AM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	20-15-20058-0016		
 Energy credits not met5 still needed. Blower door at 4.0 will satisfy Efficient ventilation credit of .5 Plumbing ok Sewer ok Blower door at 4.85-ok Smoke and CO detectors ok Gas appliances ok Fire sprinkler final ok 			
INSTRUCTIONS: Builder is hoping to meet 4.0 blower door to make energy credits for final. Results of test will be sent to email and card will be signed for Occupation if passing			
NEXT INSPECTION:	N/A		
RE-INSPECTION FEE	DUE? NO YES	PAID PRIOR TO SCHE	\$ DULING A RE-INSPECTION
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS: <u>iessica.contratto</u> @co.kittitas.wa.us			

http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx

411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506