INSPECTION REPORT

INST ECHION NEI ON			
PERMIT NUMBER:	BP-15-00553	OWNER'S NAME:	NASH
DATE:	3/31/2016	TYPE:	Insulation
TIME STARTED:	2:21 PM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	20-15-29050-0041		
•	ction ok be seen before cover d loft floor insulation ok		
INSTRUCTIONS: ok to cover all but fireplace			
NEXT INSPECTION:	fireplace		
RE-INSPECTION FEE	DUE? NO YES		\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL			
		essica.contratto @	

INSPECTION REQUEST LINE: 509-962-7694

http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx
411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506