INSPECTION REPORT

PERMIT NUMBER: BP-15-00564 OWNER'S NAME: VAN TILBURG

DATE:		10/7/2015	TYPE:	Radiant heat	
TIME STARTED:		4:12 PM	INSPECTOR:	Jessica Contratto	
MAP NUMBER:		21-14-09058-0004			
	1. Hydronics at 100#-ok				
2. Slab insulation ok					
INCTO	LICTIONS: C	N. t			
INSTRUCTIONS: Ok to pour					
NEXT INSPECTION: floor framing or sharwalls					
RE-IN	SPECTION FEI	E DUE? NO	YES	\$	
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION					
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:					
	iessica.contratto @co.kittitas.wa.us				
	• INSPECTION REQUEST LINE: www.co.kittitas.wa.us/cds/request.asp or 509-962-7694 •				
411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506					