INSPECTION REPORT

PERMIT NU	IMBER:	BP-15-00631	OWNER'S NAME:	JOHNSON	
DATE:		10/2/2015	TYPE:	Framing and mechanica	
TIME STARTED:		1:09 PM	INSPECTOR:	Jeremy Haberman	
MAP NUM	BER:	18-19-30059-0005			
1. N	Mechanical Not Supply/Return Not Complete.				
2. N	2. Mechanical Exhaust Venting OK.				
3. F	3. Fireplace Rough In OK.				
4. 0	4. Gas Line Not Complete/Not on Test.				
5. T	5. Trusses OK.				
6. F	6. Pantry/Master Bedroom Not Per Plan. M.Bedroom Slider Door Header Requires (3) 2x12				
INSTRUCTIONS: Make Corrections Above. OK to Insulate.					
NEXT INSPECTION: Insulation.					
RE-INSPECTION FEE DUE? VES \$					
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION					
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:					
ieremv.haberman @co.kittitas.wa.us					
 INSPECTION REQUEST LINE: www.co.kittitas.wa.us/cds/request.asp or 509-962-7694 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 Main Office Line: 509-962-7506 					