## **INSPECTION REPORT**

PERMIT NUMBER:	BP-15-00706	OWNER'S NAME:	DAKOTA HEIGHTS LLC
DATE:	9/29/2016	TYPE:	Rough-in mechanical
TIME STARTED:	2:34 PM	INSPECTOR:	Jeremy Haberman
MAP NUMBER:	19-16-06052-0009		
<ol> <li>Gas Line at 25#/15min. OK.</li> <li>Suppy/Return Venting Missing Termination Near Garge Entry.</li> <li>Exhaust Ducting OK. FANS NOT INSTALLED AT THIS TIME.</li> </ol>			
INSTRUCTIONS: OK to Call For Framing Once Electrical Inspection Is Completed.  NEXT INSPECTION: Framing			
RE-INSPECTION FEE			\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL  ADDRESS: <u>ieremv.haberman</u> @co.kittitas.wa.us			
INSPECTION PROLIEST LINE: FOO 962 7694			

http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506