INSPECTION REPORT

PERMIT NUMBER:	BP-15-00792	OWNER'S NAME:	NELSON-KAPLAN
DATE:	11/4/2016	TYPE:	Mechanical and plumbir
TIME STARTED:	4:33 PM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	20-15-13050-0002		
 Garage section missing 6x6 posts at 4 corners. Marked on plan page S201 Engineer to clarify MSTA 36 strap placement on S201. 3 places. Drag strut?? Not currently installed Detail 15/S901 not installed. Not called on plan. Required??? 			
INSTRUCTIONS: Correct above			
NEXT INSPECTION:			
RE-INSPECTION FEE	DUE? NO YES		\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS: <u>iessica.contratto</u> @co.kittitas.wa.us			
INSPECTION REQUEST LINE: 509-962-7694 http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx			

411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506