INSPECTION REPORT

TYPE:

OWNER'S NAME: MDJ CONTRACTORS

Framing

PERMIT NUMBER: BP-15-00813

DATE:

1/7/2016

TIME STARTED:	2:58 PM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	17-18-07060-0007		
1 Framing ok			
1. Framing ok			
2. Trusses ok			
3. Complete insulation guard at chimney			
INSTRUCTIONS: ok to insulate			
NEXT INSPECTION: insulation			
RE-INSPECTION FEI	E DUE? V NO	YES	\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:			
iessica.contratto @co.kittitas.wa.us			
• INSPECTION REQUEST LINE: www.co.kittitas.wa.us/cds/request.asp or 509-962-7694 •			
411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506			