INSPECTION REPORT

PERMIT NUMBER:	BP-15-00878	OWNER'S NAME:	STRATTON
DATE:	3/17/2017	TYPE:	Mechanical
TIME STARTED:	2:28 PM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	16-20-03000-0009		
1. Fireplace ok 2. Exhaust fans 3. Gas at 20#-ok 4. Mini split roug			
INSTRUCTIONS:			
NEXT INSPECTION:	Framing		
RE-INSPECTION FEE	DUE? NO YES		\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS: <u>iessica.contratto</u> @co.kittitas.wa.us			
INSPECTION REQUEST LINE: 509-962-7694 http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx			

411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506