INSPECTION REPORT

MOI ECHOIT KEI OKI			
PERMIT NUMBER:	BP-16-00021	OWNER'S NAME:	STAGNARO
DATE:	9/22/2016	TYPE:	Mechanical
TIME STARTED:	11:43 AM	INSPECTOR:	Justin Bennett
MAP NUMBER:	20-14-12065-0011		
1. Exhaust Ok 2. Verify dryer vent @ insulation			
INSTRUCTIONS: Verify dryer vent @ insulation			
NEXT INSPECTION:	Framing		
RE-INSPECTION FEE	DUE? NO YES		\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL			
	ADDRESS: <u>justin.bennett</u> @co.kittitas.wa.us		

INSPECTION REQUEST LINE: 509-962-7694

http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx
411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506