INSPECTION REPORT

PERMIT NUMBER:	BP-16-00072	OWNER'S NAME:	CHRISTIANSON
DATE:	3/8/2016	TYPE:	Final
TIME STARTED:	10:01 AM	INSPECTOR:	Justin Bennett
MAP NUMBER:	17-18-04052-0001		
2. Water heater	eeds to be 15#/15 mins and supply gas line not installed llation not complete		
INSTRUCTIONS: Pump up gas line/Re-Inspection/Complete Install/Final Inspection NEXT INSPECTION: Re-Inspection RE-INSPECTION FEE DUE? NO YES \$			
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
	QUESTIONS? PLEASE CONTACT THE I	NSPECTOR AT THE FO	LLOWING E-MAIL
	ADDRESS:	iustin.bennett @	co.kittitas.wa.us

INSPECTION REQUEST LINE: 509-962-7694

http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506