INSPECTION REPORT

PERMIT NUMBER:	BP-16-00078	OWNER'S NAME:	VAN WERT
DATE:	11/4/2016	TYPE:	Multiple (see notes)
TIME STARTED:	2:23 PM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	20-15-22000-0012		
1. Plumb/mech p 2. Gas at 18#-ok 3. Fireplace not i 4. Mechanical ok 5. DWV at 7#-ok 6. H20 at 50#-ok	c installed yet. Fresh air verified ro c k	ughed in	
INSTRUCTIONS:			
NEXT INSPECTION:	Framing		
RE-INSPECTION FEE	DUE? NO YES		\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS: <u>iessica.contratto</u> @co.kittitas.wa.us			
INSPECTION REQUEST LINE: 509-962-7694 http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx			

411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506