INSPECTION REPORT

OWNER'S NAME: SELZLER

PERMIT NUMBER: BP-16-00113

DATE:	8/5/2016	TYPE:	Mechanical and plumbir
TIME START	ED: 9:32 AM	INSPECTOR:	Mike Flory
MAP NUMB	er: 19-15-04052-0003		
1. H2O O 2. DWV C 3. LP Gas 4. Gater v)K	ee at insulation insp.	
INSTRUCTIO	ons: Next inspection Framing.		
NEXT INSPE	CTION: Framing		
RE-INCDECT	ION FEE DUE? NO	YES	\$
RE-INSPECT	Ľ		
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
		FACT THE INSPECTOR AT THE FO	
	ADDRESS:		co.kittitas.wa.us
INSPECTION REQUEST LINE: 509-962-7694			
http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx			
411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506			