INSPECTION REPORT

PERMIT NUMBER:	BP-16-00113	OWNER'S NAME:	SELZLER
DATE:	12/1/2016	TYPE:	Final
TIME STARTED:	3:46 PM	INSPECTOR:	Justin Bennett
MAP NUMBER:	19-15-04052-0003		
 Plumbing Ok Water Heater Ok FLS Ok Energy Credits Ok Fire Separation Ok Blower Door not complete 			
INSTRUCTIONS: Complete Blower Door Test/Once complete Ok to issue C of O			
NEXT INSPECTION:	Administrative Final		
RE-INSPECTION FEE DUE? YES \$			
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL			
	QUESTIONS? PLEASE CONTACT THE ADDRESS:	INSPECTOR AT THE FO iustin.bennett @	
		<u>,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,</u>	

INSPECTION REQUEST LINE: 509-962-7694

http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506