INSPECTION REPORT

PERMIT NUMBER:	BP-16-00114	OWNER'S NAME:	MDJ CONTRACTORS
DATE:	4/22/2016	TYPE:	Framing
TIME STARTED:	1:01 PM	INSPECTOR:	Justin Bennett
MAP NUMBER:	17-18-08058-0006		
2. Exhaust fans3. Trusses Ok) 7# - Needs to be 15#/15 mins still not terminated needs to be insulated - verify @	insulation	
INSTRUCTIONS: Ok to insulate			
NEXT INSPECTION:	Insulation		
RE-INSPECTION FEE			\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
	QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:		

INSPECTION REQUEST LINE: 509-962-7694

http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx
411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506