INSPECTION REPORT

PERMIT NUMBER:	BP-16-00114	OWNER'S NAME:	MDJ CONTRACTORS
DATE:	6/8/2016	TYPE:	Final
TIME STARTED:	10:09 AM	INSPECTOR:	Justin Bennett
MAP NUMBER:	17-18-08058-0006		
 Install/repair crawl visqueen Make safe exterior electrical Maintain fire separation @ garage (Water heater piping) Access not approved Fireplace not installed OA for fireplace not installed Complete electrical cover plate installation Install smoke/CO outside of master bedroom (currently smoke) Gas has not been inspected Blower door Ok Insulation Ok Plumbing Ok Fireplace rough in never completed Verify OA to return for HVAC (in progress) 			
INSTRUCTIONS: Complete above corrections/Re-Inspection			
NEXT INSPECTION: Re-Inspection			
RE-INSPECTION FEE DUE? VES \$			
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS: <u>iustin.bennett</u> @co.kittitas.wa.us			

INSPECTION REQUEST LINE: 509-962-7694

http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506