



KITTITAS COUNTY COMMUNITY DEVELOPMENT SERVICES

## INSPECTION REPORT

PERMIT NUMBER: BP-16-00134

OWNER'S NAME: WEISBECK

DATE: 3/31/2017

TYPE: Mechanical and plumbir

TIME STARTED: 11:45 AM

INSPECTOR: Amber Green

MAP NUMBER: 17-18-03011-0018

	1. Post down under girder trusses in front bedroom.
	2. Complete range vent piping.
	3. Fireplace not installed at time of this inspection, can be seen later.
	4. DWV (5#/1hr) - OK
	5. H2O (60#/15min) - OK
	6. Gasline (18#/2hr) - OK

INSTRUCTIONS: Maintain headroom at beam in living area. OK to Insulate.

NEXT INSPECTION: Insulation

RE-INSPECTION FEE DUE?



NO



YES

\$ \_\_\_\_\_

**IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION**

QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:

\_\_\_\_\_ [amber.green@co.kittitas.wa.us](mailto:amber.green@co.kittitas.wa.us)

• INSPECTION REQUEST LINE: [www.co.kittitas.wa.us/cds/request.asp](http://www.co.kittitas.wa.us/cds/request.asp) or 509-962-7694 •

411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506