## **INSPECTION REPORT**

IIIOI ECITORI NEI ORI			
PERMIT NUMBER:	BP-16-00206	OWNER'S NAME:	KARN
DATE:	1/20/2017	TYPE:	Mechanical
TIME STARTED:	10:49 AM	INSPECTOR:	Justin Bennett
MAP NUMBER:	22-11-09054-0061		
<ol> <li>Mechanical O</li> <li>Install FSK pa</li> <li>Fireplace RI O</li> <li>Interior Shear</li> <li>Framing Ok</li> </ol>	per @ exterior insulation behind in the control of	fireplace	
INSTRUCTIONS: Ok to insulate			
NEXT INSPECTION:	Insulation		
RE-INSPECTION FEE	DUE? NO YES		\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
	QUESTIONS? PLEASE CONTACT THE I	NSPECTOR AT THE FO	LLOWING E-MAIL
	ADDRESS:	iustin.bennett @	co.kittitas.wa.us

**INSPECTION REQUEST LINE: 509-962-7694** 

http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx
411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506