INSPECTION REPORT

PERMIT NUMBER:	BP-16-00247	OWNER'S NAME:	MDJ CONTRACTORS I
DATE:	11/29/2016	TYPE:	Mechanical and plumbir
TIME STARTED:	10:59 AM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	17-18-07060-0003		
1. Gas at 35#/15 2. Supply and re 3. Exhaust ok 4. Plumbing insta	turn duct ok		
INSTRUCTIONS:			
NEXT INSPECTION:	Plumbing		
RE-INSPECTION FEE DUE? V NO YES \$ IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS: <u>iessica.contratto</u> @co.kittitas.wa.us			
INSPECTION REQUEST LINE: 509-962-7694 http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506			