INSPECTION REPORT

INST ECTION KET OKT			
PERMIT NUMBER:	BP-16-00268	OWNER'S NAME:	BARGE
DATE:	6/23/2017	TYPE:	Mechanical and plumbir
TIME STARTED:	12:53 PM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	22-11-15052-0014		
 Gas at 15#-ok DWV on stack-ok H20 at 50#-ok Exhaust fans ok Primer will be vapor barrier primer that meets perm rating Fireplace rough-ins ok. Chimneys need to be seen before cover Interior shear wall for correction ok 			
INSTRUCTIONS: Ok to cover			
NEXT INSPECTION:	Chimneys		
RE-INSPECTION FEE DUE? IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS: <u>iessica.contratto</u> @co.kittitas.wa.us			

INSPECTION REQUEST LINE: 509-962-7694

http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx
411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506