INSPECTION REPORT

INST ECTION KET OKT			
PERMIT NUMBER:	BP-16-00281	OWNER'S NAME:	O'BRIEN
DATE:	1/26/2017	TYPE:	Mechanical and plumbir
TIME STARTED:	2:34 PM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	20-14-14050-0929		
 Alarms are low voltage system Inspection is for final Garage door to residence to be self closing/latching Step down to garage cannot exceed 7 3/4" from threshold Handrails not installed at stairs to bonus room Sewer connection letter from Tumble Creek needed Fireplaces ok Plumbing ok Energy credits met INSTRUCTIONS: Complete above, re-inspection			
NEXT INSPECTION: Re-inspect			
RE-INSPECTION FEE	DUE? NO YES		\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS: iessica.contratto @co.kittitas.wa.us			

INSPECTION REQUEST LINE: 509-962-7694

http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx
411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506