INSPECTION REPORT

PERMIT NUMBER:	BP-16-00303	OWNER'S NAME:	MINERS CAMP
DATE:	11/2/2016	TYPE:	Mechanical and plumbir
TIME STARTED:	12:36 PM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	20-15-19000-0021		
1. Gas at 30#-ok 2. DWV on stack 3. H20 at 70#-ok 4. Fireplace ok 5. Supply and re 6. Exhaust fans	turn ok		
INSTRUCTIONS:			
NEXT INSPECTION:	Framing		
RE-INSPECTION FEE	DUE? V NO YES		\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:			
INSPECTION REQUEST LINE: 509-962-7694			
http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx			
411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506			