INSPECTION REPORT

PERMIT NUMBER:	BP-16-00322	OWNER'S NAME:	SHAW
DATE:	6/10/2016	TYPE:	Stove or fireplace
TIME STARTED:	9:50 AM	INSPECTOR:	Justin Bennett
MAP NUMBER:	18-19-08030-0025		
Fireplace Rough In Ok Install combustion air below fire box			
INSTRUCTIONS: Confirm combustion air @ Final			
NEXT INSPECTION:	Final		
RE-INSPECTION FEE			\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
	QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS: <u>justin.bennett</u> @co.kittitas.wa.us		
	ADDI(L33	iusiiii.Deliiieil @	CO.NILLILAS.WA.US

INSPECTION REQUEST LINE: 509-962-7694

http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506