## **INSPECTION REPORT**

IIII ECHON KEI OKI			
PERMIT NUMBER:	BP-16-00463	OWNER'S NAME:	ROSE
DATE:	4/17/2017	TYPE:	Framing
TIME STARTED:	12:04 PM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	17-23-19010-0004		
<ol> <li>Provide LGT4 connection at girder truss to top plate in living room per note page S3. Truss screws used in lieu. Provide engineer approval</li> <li>Condensate drain on air handler runs uphill after leaving unit. Shorten vertical run of pipe to provide proper slope</li> </ol>			
INSTRUCTIONS: Ok to insulate			
NEXT INSPECTION: insulation			
RE-INSPECTION FEE	DUE? NO YES		\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL  ADDRESS: Jessica contratto @co kittitas wa us			

**INSPECTION REQUEST LINE: 509-962-7694** 

http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx
411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506