INSPECTION REPORT

PERMIT NUMBER:	BP-16-00578	OWNER'S NAME:	FRERKS
DATE:	5/15/2017	TYPE:	Insulation
TIME STARTED:	10:40 AM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	20-17-28063-0007		
1. Wall insulation 2. Foam flash wi			
INSTRUCTIONS: OF			
Interior shear in garage			
RE-INSPECTION FEE		DAID DDIOD TO SCUE	\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL			

INSPECTION REQUEST LINE: 509-962-7694

ADDRESS:

http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506

<u>iessica.contratto</u> @co.kittitas.wa.us