INSPECTION REPORT

PERMIT NUMBER:	BP-16-00630	OWNER'S NAME:	DK PROFESSIONAL
DATE:	5/9/2017	TYPE:	Plumbing
TIME STARTED:	12:39 PM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	20-14-12068-0007		
1. H20 at 65#-liv 2. DWV test plug 3. Gas at 20#-ok	g blew out. Not on test		
INSTRUCTIONS: Re-test DWV. Can be seen at next inspection			
NEXT INSPECTION:	Frame/mech/DWV		
RE-INSPECTION FEE	DUE? NO YES		\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL			
	ADDRESS:ji	essica.contratto @	co.kittitas.wa.us

INSPECTION REQUEST LINE: 509-962-7694

http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx
411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506