## **INSPECTION REPORT**

PERMIT NUMBER:	BP-16-00675	OWNER'S NAME:	KONO
DATE:	4/21/2017	TYPE:	Mechanical
TIME STARTED:	11:24 AM	INSPECTOR:	Justin Bennett
MAP NUMBER:	20-15-19050-0038		
1. Install nail plates/straps @ HVAC penetration of top and bottom plate 2. Supply and Return Ok 3. Outside Air confirmed 4. Exhaust Fans Ok 5. DWV on Stack - Ok 6. Supply @ 80#/15 mins - Ok 7. Plumbing RI Ok 8. Gas @ 25#/15 mins - Ok			
NEXT INSPECTION: Framing			
RE-INSPECTION FEE			\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL			

**INSPECTION REQUEST LINE: 509-962-7694** 

ADDRESS:\_

http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506

iustin.bennett @co.kittitas.wa.us