## **INSPECTION REPORT**

PERMIT NUMBER:	BP-16-00675	OWNER'S NAME:	KONO
DATE:	5/10/2017	TYPE:	Framing
TIME STARTED:	11:22 AM	INSPECTOR:	Justin Bennett
MAP NUMBER:	20-15-19050-0038		
C1 Blocking over beams in Great Rm - not complete     Other corrections Ok			
INSTRUCTIONS: Complete above/Ok to insulate/Verify blocking @ insulation  NEXT INSPECTION: Insulation  RE-INSPECTION FEE DUE? V NO YES \$			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL			
	ADDRESS:	<u>iustin.bennett</u> @	co.kittitas.wa.us

**INSPECTION REQUEST LINE: 509-962-7694** 

http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx
411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506