INSPECTION REPORT

PERMIT NUMBER:	BP-16-00679	OWNER'S NAME:	HUFFMAN
DATE:	10/13/2016	TYPE:	Final
TIME STARTED:	11:48 AM	INSPECTOR:	Justin Bennett
MAP NUMBER:	18-19-18010-0001		
 Gas line to range not installed per code Shutoff will be required @ interior side of approved pipe Bonding of the approved pipe will be required NOTE: Water heater has been moved outside NOTE: WH gas line does not penetrate silo 			
INSTRUCTIONS: Complete corrections above/Place gas piping on test/Re-Inspection			
NEXT INSPECTION: Re-Inspection			
RE-INSPECTION FEE			\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:			

INSPECTION REQUEST LINE: 509-962-7694

http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506