INSPECTION REPORT

PERMIT NUMBER:	BP-16-00691	OWNER'S NAME:	MINERS CAMP
DATE:	4/11/2017	TYPE:	Exterior shear
TIME STARTED:	4:15 PM	INSPECTOR:	Jeremy Haberman
MAP NUMBER:	20-15-19060-0008		
Exterior Holdo Interior Shear	own Missing. Circled on Plan. Not Inspected.		
INSTRUCTIONS: OK to Cover Exterior. NEXT INSPECTION: Interior Shear/Plumb/Mech			
RE-INSPECTION FEE	DUE? NO YES		\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:			
INCRECTION REQUEST LINE, FOR OCA 7004			

INSPECTION REQUEST LINE: 509-962-7694

http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx
411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506