INSPECTION REPORT

| PERMIT NUMBER: | BP-16-00691 | OWNER'S NAME: | MINERS CAMP |
|--|------------------|---------------|------------------------|
| DATE: | 4/25/2017 | TYPE: | Mechanical and plumbir |
| TIME STARTED: | 12:39 PM | INSPECTOR: | Jessica Contratto |
| MAP NUMBER: | 20-15-19060-0008 | | |
| 1. Gas at 25#/15 2. DWV on stac 3. H20 at 70#-ok 4. Exhaust ok 5. Mechanical ok | k-ok | | |
| INSTRUCTIONS: | | | |
| NEXT INSPECTION: | Framing | | |
| RE-INSPECTION FEE | DUE? V NO YES | | \$ |
| IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION | | | |
| QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS: iessica.contratto @co.kittitas.wa.us | | | |
| | | | |
| INSPECTION REQUEST LINE: 509-962-7694 http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx | | | |
| 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506 | | | |
| | | | |