



KITITITAS COUNTY COMMUNITY DEVELOPMENT SERVICES

## INSPECTION REPORT

PERMIT NUMBER: BP-16-00704

OWNER'S NAME: VOGT

DATE: 10/26/2016

TYPE: Final

TIME STARTED: 2:21 PM

INSPECTOR: Justin Bennett

MAP NUMBER: 17-19-06056-0002

1. Fireplace insert rough in Ok
2. Free standing Fireplace rough in Ok
3. Gas piping @ 7# - Needs to be 15#/15 mins

INSTRUCTIONS: Re-Inspect Gas @ 15#

NEXT INSPECTION: Re-Inspection

RE-INSPECTION FEE DUE?  NO  YES \$ \_\_\_\_\_

**IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION**

QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL  
ADDRESS: justin.bennett @co.kittitas.wa.us

**INSPECTION REQUEST LINE: 509-962-7694**

<http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx>

411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506