



KITITITAS COUNTY COMMUNITY DEVELOPMENT SERVICES

INSPECTION REPORT

PERMIT NUMBER: BP-16-00734

OWNER'S NAME: MINERS CAMP

DATE: 3/21/2017

TYPE: Exterior shear

TIME STARTED: 12:31 PM

INSPECTOR: Jessica Contratto

MAP NUMBER: 20-15-19060-0002

1. Complete horizontal seam nailing at top of sheet on house wall facing adjacent residence
2. Hold down in lower shower wall missing.
3. Complete detail 11/D2 at all applicable windows per plan

INSTRUCTIONS: Complete above

NEXT INSPECTION: Re-inspect

RE-INSPECTION FEE DUE? NO YES \$ _____

IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION

QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL
ADDRESS: _____ [jessica.contratto @co.kittitas.wa.us](mailto:jessica.contratto@co.kittitas.wa.us)

INSPECTION REQUEST LINE: 509-962-7694

<http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx>

411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506