



KITTITAS COUNTY COMMUNITY DEVELOPMENT SERVICES

INSPECTION REPORT

PERMIT NUMBER: BP-16-00745

OWNER'S NAME: GEARHART

DATE: 1/5/2017

TYPE: Mechanical and plumbir

TIME STARTED: 11:36 AM

INSPECTOR: Jessica Contratto

MAP NUMBER: 22-11-15053-0020

1. Mechanical ok
2. Gas piping installed for water heater and added generator. Gas piping needs to be tested for inspection. Generator requires permitting
3. DWV on stck-ok
4. H2O at 90#-ok
5. Bath walls framing ok
6. Window framing ok
7. Complete last of insulation

INSTRUCTIONS: Ok to cover

NEXT INSPECTION: Gas piping

RE-INSPECTION FEE DUE? NO YES \$ _____

IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION

QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL
ADDRESS: _____ [jessica.contratto @co.kittitas.wa.us](mailto:jessica.contratto@co.kittitas.wa.us)

INSPECTION REQUEST LINE: 509-962-7694

<http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx>

411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506