## **INSPECTION REPORT**

INSPECTION REPORT			
PERMIT NUMBER:	BP-16-00777	OWNER'S NAME:	TALISMAN
DATE:	6/30/2017	TYPE:	Framing
TIME STARTED:	11:35 AM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	20-15-19056-0075		
1. Shield gas flex at fireplace penetration 2. Provide attic appliance access, electrical and drain pan or sensor per M1305. 1.3, M1305.1.3.1, M1411.3.1 3. Truss bracing M04, M20, T18, T19 4. Fireplace rough in ok 5. H20 is live-ok  INSTRUCTIONS: Complete above, ok to insulate			
NEXT INSPECTION: Insulation			
RE-INSPECTION FEE			\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL			

**INSPECTION REQUEST LINE: 509-962-7694** 

ADDRESS:\_\_

http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx
411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506

iessica.contratto @co.kittitas.wa.us