



KITITITAS COUNTY COMMUNITY DEVELOPMENT SERVICES

## INSPECTION REPORT

PERMIT NUMBER: BP-16-00778

OWNER'S NAME: TALISMAN

DATE: 6/30/2017

TYPE: Framing

TIME STARTED: 10:42 AM

INSPECTOR: Jessica Contratto

MAP NUMBER: 20-15-19056-0076

1. Gas flex must be shielded where penetrating fireplace cabinet
2. Truss bracing T12-14 trusses
3. H2O is live-ok
4. Fireplace rough in ok
5. Interior shearwall and straps at party wall not complete yet. Will be seen after insulation
6. Master bedroom exterior door header missing
7. Provide attic appliance access, electrical and drain pan or sensor per M1305.1.3, M1305.1.3.1, M1411.3.1

INSTRUCTIONS: Complete above, ok to insulate

NEXT INSPECTION: Insulation

RE-INSPECTION FEE DUE?



NO



YES

\$ \_\_\_\_\_

**IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION**

QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL  
ADDRESS: \_\_\_\_\_ [jessica.contratto @co.kittitas.wa.us](mailto:jessica.contratto@co.kittitas.wa.us)

**INSPECTION REQUEST LINE: 509-962-7694**

<http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx>

411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506