



KITTITAS COUNTY COMMUNITY DEVELOPMENT SERVICES

## INSPECTION REPORT

PERMIT NUMBER: BP-17-00047

OWNER'S NAME: WILSON

DATE: 6/19/2017

TYPE: Multiple (see notes)

TIME STARTED: 10:53 AM

INSPECTOR: Jessica Contratto

MAP NUMBER: 18-18-27071-0128

1. Insulation ok
2. Walls R-21 batt with kraft facing
3. Ceiling R-49 batt with poly barrier
4. Fireplace and gas line not installed yet

INSTRUCTIONS: Ok to cover except fireplace

NEXT INSPECTION: Fireplace rough-in/gas line

RE-INSPECTION FEE DUE?



NO



YES

\$ \_\_\_\_\_

**IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION**

QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL  
ADDRESS: \_\_\_\_\_ [jessica.contratto @co.kittitas.wa.us](mailto:jessica.contratto@co.kittitas.wa.us)

**INSPECTION REQUEST LINE: 509-962-7694**

<http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx>

411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506