## **INSPECTION REPORT**

MOI ECHON NEI ONI			
PERMIT NUMBER:	BP-17-00106	OWNER'S NAME:	RITTER
DATE:	6/7/2017	TYPE:	Framing
TIME STARTED:	12:43 PM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	18-18-08050-0005		
<ol> <li>Plumbing not on test</li> <li>Gas at 5#. 15# minimum required for test</li> <li>Ductless unit rough-ins ok</li> <li>Post down under double truss in garage</li> <li>Trusses ok</li> <li>Framing ok</li> </ol>			
INSTRUCTIONS: Complete above corrections, ok to insulate			
NEXT INSPECTION: Insulation/corrections			
RE-INSPECTION FEE	DUE? NO YES		\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL  ADDRESS: <u>iessica.contratto</u> @co.kittitas.wa.us			

**INSPECTION REQUEST LINE: 509-962-7694** 

http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx
411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506