INSPECTION REPORT

PERMIT NUMBER:	BP-17-00106	OWNER'S NAME:	RITTER
DATE:	6/13/2017	TYPE:	Insulation
TIME STARTED:	12:00 PM	INSPECTOR:	Justin Bennett
MAP NUMBER:	18-18-08050-0005		
MAP NUMBER: 18-18-08050-0005 1. DWV @ 0# - Needs to be 15#/15 mins 2. Post down @ double truss in garage 3. Gas @ 28#/15 mins - Ok 4. Plumbing Supply @ 95#/15 mins - Ok 5. Wall insulation - Bibbs w/ vapor barrier 6. Range Vent insulated - Ok 7. Interior Shear Ok 8. DO NOT COVER INSTRUCTIONS: DO NOT COVER/Complete above corrections			
NEXT INSPECTION: Re-Inspection			
RE-INSPECTION FEE	DUE? NO YES		\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
NEXT INSPECTION: Re-Inspection RE-INSPECTION FEE DUE? VES \$			

INSPECTION REQUEST LINE: 509-962-7694

ADDRESS:_

http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506

iustin.bennett @co.kittitas.wa.us