INSPECTION REPORT

PERMIT NUMBER: FO-14-00018 OWNER'S NAME: COBURN/CARMINE

DATE:		6/30/2014	TYPE:	Footings
TIME STARTED:		1:16 PM	INSPECTOR:	
	move vertical rebar hooks to bottom grids on fireplace footing.			
	see lower deck pier footings at foundation wall inspection			
INSTRUCTIONS: move rebar. Ok to pour footings				
NEXT INSPECTION: Foundation walls				
RE-IN	SPECTION FEI	E DUE? NO	YES	\$
	IF RE	QUIRED, RE-INSPECTION FEE	ES MUST BE PAID PRIOR TO SCH	EDULING A RE-INSPECTION
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:@co.kittitas.wa.us				
			vw.co.kittitas.wa.us/cds/req llensburg, WA 98926 ● Main Of	