INSPECTION REPORT

PERMIT NUMBER: FO-15-00054 OWNER'S NAME: NASH

DATE:	8/31/2015	TYPE:	Foundation walls	
TIME STARTED:	12:16 PM	INSPECTOR:	Jessica Contratto	
MAP NUMBER:	20-15-29050-0041			
1. walls o	k			
2. install 2	2 missing STHD14 straps	at kitchen area and gara	ge separation wall	
INICTRUCTIONS	als to noun			
INSTRUCTIONS:	ok to pour			
NEXT INSPECTION	floor framing			
RE-INSPECTION FI	EE DUE? NO	YES	\$	
IF RI	EQUIRED, RE-INSPECTION FEES	S MUST BE PAID PRIOR TO SC	HEDULING A RE-INSPECTION	
(QUESTIONS? PLEASE CONTACT			
		iessica.contratto @cc		
	ECTION REQUEST LINE: <u>ww</u> 411 N. Ruby Street, Suite 2, Ell		quest.asp or 509-962-7694 ● Office Line: 509-962-7506	
			200 001 ,000	